
MATERIAL SAFETY DATA SHEET

1.

ENGINEERING CONTROLS: Use local exhaust ventilation to control dust.

PERSONAL PROTECTIVE EQUIPMENT:

SKIN PROTECTION: For brief contact to dust, no precautions other than clean body-

